




Straight Connectors are used to transition from copper wire to Conductor Tape





Conductive Patches and Straight Connectors are heat set at 120°C for 30 seconds at 60PSI




### **T** Connector Process








Press T Connector, part 1 onto Bemis 3415 at 120°C for 30 seconds at 60 PSI, then cut away excess adhesive






## Heat set T Connector, part 1 onto garment at 120°C for 30 seconds at 60PSI






# Place circuitry from a lamp onto the contact pads of the T Connector



## Place circuitry from another lamp onto the contact pads of the T Connector



### Place circuitry from a connector lead to the remaining set of T Connector contact pads





Place T Connector, part 2 on top of part 1, ensuring the numbers and pads align, then heat set in place at 120°C for 30 seconds at 60PSI

