

Understanding Absolute Pressure Sensors

Technical Note

INTRODUCTION

Most people are typically accustomed to dealing in gage pressure, that is, pressure relative to the normal atmospheric pressure which surrounds us. As such, "absolute" pressure and absolute pressure sensors which measure pressure relative to a perfect vacuum can be somewhat confusing. Also, because zero absolute pressure (a perfect vacuum) is impossible to achieve, it is much harder to measure and calibrate absolute pressure sensors. This application note will discuss what absolute pressure is, how it is best measured and how to calibrate absolute pressure sensors.

DIFFERENTIAL (GAGE) PRESSURE

It is often easier to understand absolute pressure if we have a clear understanding of differential and gage pressure which we are generally more familiar with.

Differential pressure is the pressure difference measured between two pressure sources. This is usually expressed in pounds per square inch differential (psid). When one source is the ambient pressure, this is then called gage or relative pressure and is typically expressed in pounds per square inch gage (psig). Therefore, gage pressure is simply a special case of differential pressure with pressures measured differentially but always relative to the local ambient pressure. In the same respect, absolute pressure can also be considered a differential pressure where the measured pressure is compared to a perfect vacuum.

ABSOLUTE PRESSURE

Absolute pressure sensors are most commonly used to measure changes in barometric pressure or as altimeters. These applications require reference to a fixed pressure as they cannot be simply referenced to the surrounding ambient pressure.


Absolute pressure is defined as the pressure measured relative to a perfect vacuum. For example, 10 pounds per square inch absolute (psia) would be 10 psi above a perfect vacuum. This is roughly 4.7 psi below the standard atmospheric pressure at sea level of 14.7 psia. 0 psia is then the pressure of a perfect vacuum.*

Honeywell's absolute pressure sensors are made by hermetically sealing a vacuum reference chamber on one side of the integrated circuit sensing element. (See Figure 1) Pressures to be measured are then

measured relative to this vacuum reference. The actual "vacuum" which is sealed into the sensor is approximately 0.0005 psia (25 millitorr). Using this near vacuum as a reference eliminates any potential thermal errors which would occur if any gas was trapped in the reference chamber as it would exert a pressure during expansion and contraction with temperature in accordance with Boyles law. One of the advantages of integrated circuit sensors is the small volume of trapped vacuum reference which, in conjunction with a reliable silicon-to-silicon hermetic seal, makes these devices time and temperature stable.

FIGURE 1

Cross Sectional View of an Intergrated Circuit Sensor Element



CALIBRATING ABSOLUTE SENSORS

To use any sensor in an absolute application, we must be able to accurately calibrate the device for offset and span. This requires understanding offset and span in terms of absolute pressure.

OFFSET VOLTAGE

The Offset voltage is defined as the sensor's output at *zero differential pressure*. For gage sensors, this is the output with ambient pressure (0 psig) applied to the sensor. As such, offset voltages are relatively easy to measure for gage sensors. However, for an absolute device, the offset voltage is the output voltage of the sensor with a perfect vacuum (0 psia) applied to the sensor. This means that with normal atmospheric pressure applied to the absolute sensor, there will be an output voltage which corresponds to approximately 14.7 psia at sea level.

*Footnote: For illustration purposes in this note, pounds per square inch (psi) is used as the unit of pressure measure. This unit can obviously be converted to other common pressure units such as mmHg, kPa, bar, etc.. (See the attached chart for individual conversion factors.)

Once the offset is adjusted, span is set using either the highest reference pressure available or where maximum accuracy is required. The 15 psig reference point is used here as an example. Span adjustment should be made to set the output at 15 psig (V_{02}) to 4.933 volts. This is 29.60 psi times the ideal sensitivity of 0.1667 volts per psi ($5.00 \text{ volts}/30 \text{ psi} = 0.1667 \text{ V/psi}$).

To complete the calibration process, we can now check and fine tune, if necessary, the offset reading.

CONCLUSION

Although absolute pressure sensors are perhaps not as well understood or easily calibrated as gage pressure devices, by using barometric pressure as a reference in conjunction with any other reference point, gage or absolute, absolute pressure devices can be accurately calibrated.

PRESSURE UNIT CONVERSION CONSTANTS (Most Commonly Used – Per International Conventions)

	PSI ⁽¹⁾	In. H ₂ O ⁽²⁾	In. Hg ⁽³⁾	kPa	millibar	cm H ₂ O ⁽⁴⁾	mm Hg ⁽⁵⁾
PSI ⁽¹⁾	1.000	27.680	2.036	6.8947	68.947	70.308	51.715
In. H ₂ O ⁽²⁾	3.6127×10^{-2}	1.000	7.3554×10^{-2}	0.2491	2.491	2.5400	1.8683
In. Hg ⁽³⁾	0.4912	13.596	1.000	3.3864	33.864	34.532	25.400
kPa	0.14504	4.0147	0.2953	1.000	20.000	20.2973	7.5006
millibar	0.01450	0.40147	0.02953	0.100	1.000	1.01973	0.75006
cm H ₂ O ⁽⁴⁾	1.4223×10^{-2}	0.3937	2.8958×10^{-2}	0.09806	0.9806	1.000	0.7355
mm Hg ⁽⁵⁾	1.9337×10^{-2}	0.53525	3.9370×10^{-2}	0.13332	1.3332	1.3595	1.000

Notes: 1. PSI — pounds per square inch 2. at 4 °C [39 °F] 3. at 0 °C [32 °F] 4. at 4 °C [39 °F] 5. at 0 °C [32 °F] 6. 1 Torr=1 mmHg

WARRANTY/REMEDY

Honeywell warrants goods of its manufacture as being free of defective materials and faulty workmanship. Contact your local sales office for warranty information. If warranted goods are returned to Honeywell during the period of coverage, Honeywell will repair or replace without charge those items it finds defective. **The foregoing is Buyer's sole remedy and is in lieu of all other warranties, expressed or implied, including those of merchantability and fitness for a particular purpose.**

Specifications may change without notice. The information we supply is believed to be accurate and reliable as of this printing. However, we assume no responsibility for its use.

While we provide application assistance personally, through our literature and the Honeywell web site, it is up to the customer to determine the suitability of the product in the application.

For application assistance, current specifications, or name of the nearest Authorized Distributor, check the Honeywell web site or call:

1-800-537-6945 USA/Canada
1-815-235-6847 International

FAX

1-815-235-6545 USA

INTERNET

www.honeywell.com/sensing
info.sc@honeywell.com

Honeywell

Sensing and Control
www.honeywell.com/sensing

Honeywell

11 West Spring Street

Freeport, Illinois 61032

008116-1-EN IL50 GLO 1104 Printed in USA

Copyright 2004 Honeywell International Inc.

All Rights Reserved