

WEBSITE:	sparkfun.com	ໂວບວ	284.0979 [general]	Р
6175 LONGBOW DRIVE, SUITE 200 BOULDER. COLORADO USA	ZIP CODE: 80301	၂၂၁၂၁	443.0048	E

Common Mistakes with XBee Radios by Rob Faludi

SparkFun Electronics Summer Semester

Common XBee Mistakes

Your XBee project isn't working? Here are some common mistakes that both beginners and experts make:

- Not using the latest firmware (especially if ATD0 or ATIR is giving an error)
- No reference voltage to VREF pin on the 802.15.4 radios (analog and digital reads give wrong values)
- Forgetting that AT commands use hexadecimals
- Hitting return after +++ (or otherwise not respecting 1 second default guard time)
- Conversely, _not_ hitting return after an AT command
- Letting the XBee time out of command mode before issuing an AT command (you'll know because you get no response)
- Forgetting to write the configuration to firmware with ATWR (unless your application configures the radio interactively)
- Not using ATRE (restore factory defaults) before re-configuring a previously used radio (previous settings lurk unless you manually reset them all)
- Looking for analog output on the analog input pins instead of pins 6 and 7 (P0, P1)
- Using a voltage regulator without decoupling capacitors (10uF on input, 1uF on output is good)
- Mixing up TX and RX pins (fastest way to check this is switch the wires and see if it starts working)
- Using ZigBee version (ZB Pro or ZNet 2.5) when 802.15.4 version would do just fine (if you don't need to make a mesh network)
- Trying to read more than 1.2 Volts on the ZB Pro and ZNet 2.5 analog inputs (that's the limit)
- Buying Pro radios when you don't need them. (Cost more, bigger, use a lot more battery)
- Deciding the XBees are flaky. (You may not be using them correctly, but they are very reliable)



 WEBSITE: sparkfun.com

 6175 LONGBOW DRIVE, SUITE 200

 GUILDER. COLORADO
 USA

 JUNCK
 USA

Common Mistakes with XBee Radios by Rob Faludi

SparkFun Electronics Summer Semester

- Deciding an XBee is burned out when it's set to a different baud rate (check ON and ASSC lights)
- Deciding an XBee is burned out when it is just sleeping (Check ON light to see if it blinks occasionally)
- Forgetting to supply power or ground (ON light may go on and ASSC light may blink but both will be significantly dimmer)
- Not contacting Digi sooner for <u>support</u>, especially if your radio seems dead or you keep getting an error you don't understand.
- XBee Arduino Mistakes
- Sending continuously without any delay (try 10ms delay)
- Not removing RX and TX connections before uploading code (Arduino will give an error)
- Not removing RX connection when reseting, if you are continuously receiving data. (Arduino will never reset)
- XBee LilyPad Mistakes
- Hooking up more than 4 Volts to the 3.3V pin
- Using switches without pull-down resistors (but not if you use the internal pull-ups)
- Not using a pull-up or pull-down resistor on pins 5 and 7 (these don't have internal pull-ups at all)
- Using sensors without voltage divider resistors (if your sensor needs that circuit)
- Using too-resistive conductive thread for power and ground (try fabric or wires)
- Windows and <u>X-CTU</u> are required for firmware upgrades