



## Triple Axis Accelerometer – LIS3DH

Default 7-bit Unshifted Address: 0x19




## Power LED

Cut jumper to turn off power LED




## Connectors




## I<sup>2</sup>C Pull-Ups

Cut jumper to remove pull-up resistors.



## Testpoints



Designed by: Elias Santistevan

SparkFun Electronics

Sheet: /

File: SparkFun\_LIS3DH\_Micro.kicad\_sch

**Title: SparkFun Triple Axis Accelerometer – LIS3DH**

Size: USLetter Date: 2025-04-24

KiCad E.D.A. 9.0.2

Rev: v10

Id: 1/1